


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-251	Smoke	8/27/2009	ADS/TM	S21QQ_004MH	Dry	Yes	601.30



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-251	Smoke	8/27/2009	ADS/TM	S21QQ_004MH	Dry	Yes	601.30

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S1900_016G1	S1900_016MH	S1900_028MH	234.728	8
S21QQ_004G1	S21QQ_004MH	S1900_016MH	366.571	8

### Observations & Photos

**Obs\_ID** S1028-251-OB01

**Address** 2319 Bryant Ave


**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S21QQ\_004MH

**Comments** Smoke from cleanout in back yard. 2319 Bryant Ave.



**Picture** \S1028-251-OB01-P01.jpg

**Comments** Back of house, 2319 Bryant Ave.

**Obs\_ID** S1028-251-OB02

**Address** 2317 Bryant Ave


**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S21QQ\_004MH

**Comments** Smoke from cleanout in back yard. 2317 Bryant Ave.



**Picture** \S1028-251-OB02-P01.jpg

**Comments** Back of house, 2317 Bryant Ave.

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-251	Smoke	8/27/2009	ADS/TM	S21QQ_004MH	Dry	Yes	601.30

**Obs\_ID** S1028-251-OB03

**Address** 2311 Bryant Ave


**Status** Private

**Source** Cleanout

**Location** Paved concrete

**Nearest MH** S21QQ\_004MH

**Comments** Smoke from cleanout in paved concrete behind house. 2311 Bryant Ave.



**Picture** \S1028-251-OB03-P01.jpg

**Comments** Back of house, 2311 Bryant Ave.